

## Field Observation Report #23

---

Date: July 2, 2014  
Time: 3:00 pm  
Weather: Partly Cloudy  
Temperature: 70 degrees  
% Complete: 90% Visible  
Trades: Windows, Mech, Elect,  
Crew Size: 8-10

Project: Burleigh County Shop  
Project No: 12-04  
Location: Bismarck, ND

---

*The following information is a documentation of observations and findings as a result of a visit to the construction site. Items and decisions made within this reports are considered a part of the contract documents.*



*Photo 1: View from the road*



*Photo 2: The curb is being poured this week.*



*Photo 3: the entry curtain wall windows are under construction*



*Photo 4: Hose Reels and other equipment is being placed*



*Photo 5: The owner work in Phase 1 is underway.*




Photo 6: A view of the welding bay.

1. The owner is starting Phase 2 of their site work on July 7<sup>th</sup>. Capital City Construction agreed to have their equipment and the site cleaned in time, all trades will need to follow suit.
2. Permanent power is expected to be connected this week.
3. Fuel storage tanks have arrived on-site, painting continues and revisions are being made to the reception counter.

This concludes Field Observation Report #23. Please report any discrepancies to our office within 5 days.

Thank you,

  
Jennifer Jackson